



# Certificate of Compliance

This certificate is issued for the following:

**Alarm Check Valves**  
**Model H**  
(see attached sheet)

**Prepared for:**

HD Fire Protect Pvt. Ltd.  
K-98, Ajanta Road  
Jalagon - 425 003, India

**Manufactured at:**

HD Fire Protect Pvt. Ltd.  
K-98, Ajanta Road  
Jalagon - 425 003, India

FM Approvals Class: 1041, dated February 2006

Approval Identification: 0003047475

Approval Granted: October 4, 2013

To verify the availability of the Approved product, please refer to [www.approvalguide.com](http://www.approvalguide.com)

Said Approval is subject to satisfactory field performance, continuing Surveillance Audits, and strict conformity to the constructions as shown in the Approval Guide, an online resource of FM Approvals.

A handwritten signature in dark ink, appearing to read 'Richard B. Dunne', is written over a horizontal line.

Richard B. Dunne  
Group Manager – Fire Protection  
FM Approvals  
1151 Boston-Providence Turnpike  
Norwood, MA 02062



*Member of the FM Global Group*



# Certificate of Compliance

## Models H

<i>Product Designation</i>	<i>Description</i>	<i>Nominal Pipe Size, in. (mm)</i>	<i>Max Working Pressure, psi (kPa)</i>	<i>Remarks</i>
Model H	Alarm Check Valve, Flanged Ends	3, 4, 6 (80, 100, 150)	250 (1725)	a, b, c
Model H	Alarm Check Valve, Flanged Ends	8 (200)	200 (1380)	a, b, c
Model H	Alarm Check Valve, Grooved Ends	3, 4, 6 (80, 100, 150)	250 (1725)	a, b, c
Model H	Alarm Check Valve, Grooved Ends	8 (200)	200 (1380)	a, b, c
Model H	Alarm Check Valve, Flanged x Grooved Ends	3, 4, 6 (80, 100, 150)	250 (1725)	a, b, c
Model H	Alarm Check Valve, Flanged x Grooved Ends	8 (200)	200 (1380)	a, b, c

- a. Resilient seat.
- b. With Model RC9 retard chamber.
- c. Vertical installation only.



Member of the FM Global Group